




Company Registration No: 201806506H  
NEA Cleaning Business License: NEA181012/6506H/N01  
A-CORE Engineering Company Pte Ltd  
High Street Center, #17-02, 1 North Bridge Road,  
Singapore 179094  
M: Anthony Lee 9388 0684  
E: [info@acoresg.com](mailto:info@acoresg.com)  
W: <http://www.acoresg.com/>


Date: Jan 12, 2019

### Fitness center deep and detail cleaning work report



High area HEPA vacuuming (the filter is 99.97% efficient at filtering particulates down to 0.3  $\mu\text{m}$  or 0.0003mm, and without stirring up the dust when vacuuming).

Video: <https://youtu.be/CvKoZ5qlmJk>



Before




After




Before



After




Dust build up on the top of aircon unit. Before and after. Video: <https://youtu.be/ZbpFg5kYCTc>



Dust building up on overhead trays Before and after




Wall cleaning



Rack cleaning



Hard water stain (on shower screen) is removed




Cleaning for all mirrors, glass panels, glass doors



Ventilation fan cleaning



Steam cleaning(180°C) for gym mat. Work in progress: [https://youtu.be/s\\_VM3AEOexE](https://youtu.be/s_VM3AEOexE)



Wet extraction with disinfectant. Work in progress: <https://youtu.be/1qY7SrlxRj8>  
How dirty is the carpet? Please view: <https://youtu.be/pizJtZcSn6M>



Cleaning for all benches, seats with 704 disinfectant



Degreasing for treadmills



Before and after



Disinfecting lockers and high touch points with ULV fogging/UVC sterilizer  
Video: [https://www.youtube.com/watch?v=mW2MAp-Ez\\_o](https://www.youtube.com/watch?v=mW2MAp-Ez_o)

Barbell/weight sets and equipment de-rusting:



Before



After



Can you tell the difference?



Thank you!

~End~